



TEST CERTIFICATE

| | | | |
|--------------------|-----------------------|------------------|-----------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 07 Mar 2022, 14:11:30 |
| Transaction Number | 50777494 (CC10006) | Queue Number | 312309 |



| | |
|------------------|-------------------|
| Chassis Number | JMYHNP13WCA700299 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Mitsubishi |
| Model | L 300 |
| Model Year | 2012 |
| Color | White |
| Mileage | 194367 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|----------------------------|
| 01 Body | | جسم المركبة |
| 01.A Roof | PORTION RUSTY | السقف |
| 01.B Paint | BODY PORTION REPAINTED,PORTION REPAIRED,BODY MINOR DENT,SCRATCHES,PORTION RUSTY | الصبغ |
| 01.C Other | FRONT LEFT SIDE FENDER FRAME ,BULK HEAD,BUMPER FRAME,FIRE WALL REPAIRED | اخرى |
| 01.D Fenders | PORTION REPAIRED, REPAINTED | مدكار |
| 01.E Doors | PORTION REPAIRED, REPAINTED | أبواب |
| 01.F Bonnet | PORTION REPAIRED, REPAINTED | غطاء المحرك |
| 01.G Trunk | PORTION REPAIRED, REPAINTED | صندوق |
| 01.H Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 01.I Rusty | UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR GETTING RUSTY | صدأ |
| 02 Interior Condition | | الحالة الداخلية |
| 02.A AC Condition | NOT WORKING | المكيف |
| 02.B Floor Matting | REAR FLOOR MATTING DAMAGED | فرش الأرضية |
| 03 Tires and Rims Condition | | الاطارات |
| 03.A Rear Tyre | BOTH SIDE 2019 CRACKED | الاطار الخلفي |

| DEFECT | REMARKS | |
|----------------------------------|---|--------------------|
| 03.B Front Tyre | BOTH SIDE 2019 CRACKED | الاطار الامامي |
| 04 Seats Condition | | المقاعد |
| 04.A Seat Condition | SEATS COVER DAMAGED | حالة المقاعد |
| 05 Lights | | الاضاءة |
| 05.A Indicator & Hazard light | FRONT LEFT SIDE LOOSE | الاشارات |
| 06 Chassis Condition | | الشاسي |
| 06.A Chassis | FRONT LEFT SIDE CHASSIS EXTENSION REPAIRED,MINOR BEND | الشاسيه |
| 07 Engine Condition | | المحرك |
| 07.A Visual Engine Condition | OIL LEAK,ABNORMAL NOISY | حالة المحرك النظري |
| 07.B Mount | MOUNT BUSHES CRACKED | كرسي |
| 08 Transmission Condition | | الجير |
| 08.A Visual Gear Box Condition | OIL LEAK | حالة الجير النظري |
| 08.B Road Test | NOT CHECK | فحص علي الطريق |
| 08.C DIFFERENTIAL | REAR DIFFERENTIAL OIL LEAK | الدفرنشل |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

| | |
|----------------------------|-------------------|
| Change possession : | 66253783 |
| Chassis No : | JMYHNP13WCA700299 |
| Vehicle Make : | MITSUBISHI |
| Vehicle Model : | L300 |
| Vehicle Class : | Light Bus |
| Body Type : | Light Bus |
| Fuel : | Benzene |
| Color : | White, Trade name |
| Drive Direction : | -- |
| Dimensions : (H x W x L) : | -- x -- x -- |
| Current Odometer : | 194368 Kms. |
| Origin : | Japan |
| Model Year : | 2012 |
| Gear Type : | Manual |
| Engine Size : | 2000 CC |
| Engine No : | 4G63FHDPJ... |
| Horse Power : | -- |
| Axles No : | 2 |
| Cylinders : | 4 |
| No Of Doors : | 4 |
| No Of Seats : | 10 |
| G. V. W. : | 2560 Kgs. |
| Empty Weight : | 2150 Kgs. |

| | |
|---------------------------|---------------------|
| Certificate Number : | 5-TAS-2022-16338902 |
| Inspection Date : | 10-03-2022 |
| Certificate Print Date : | 10-03-2022 |
| Services : | Registration Test |
| Vehicle Testing Partner : | Tasjeel |
| Vehicle Testing Center : | Tasjeel Al Aweer |
| Total Time Taken : | 8 min 14 sec |
| Appointment Ref Number : | -- |
| Start Time : | 11:27 |
| End Time : | 11:35 |
| Lane : | 03 |
| Token No. : | 150 |
| Attempt : | 1 |
| Prints No. : | 1 |

Parameter Readings

| | | | |
|---------------------------------------|--------------------------------------|---|------------------------------|
| Service brake imbalance on front axle | Service brake imbalance on rear axle | Parking brake imbalance between LHS and RHS | Vehicle on Petrol CO Reading |
| 20 % | 17 % | 2 % | 0 % |
| Vehicle on Petrol HC Reading | | | |
| 2 PPM VOL | | | |

Inspection Findings

| Defects | Issue | Severity |
|--|--------------------------|----------|
| Engine repair engine oil leaking | Oil leaking continuously | Major |
| Speed Meter Limiter bring valid speed limited certificate | Not Calibrated | Major |

Inspection Remarks:

FRONT LEFT SIDE A,B PILLARS, FRONT LEFT SIDE FLOORING, FIRE WALL, RUNNING BOARD OLD REPAIRED. FRONT BOTH SIDE FRAME MEMBER END OLD REPAIRED,MINOR BODY DENTS & SCRATCHES

Payment Details

| | | | |
|-------------------------|-------------------|--------------------|---------------------------------|
| Inspection Performed by | Payment Method | Transaction Number | Service Fees |
| 59460 | Cash | 16338902 | AED 170 Collected on 10/03/2022 |
| Parking Slot No | Service Name | Attempt | Received by |
| -- | Registration Test | 1 | Sittu Paloth Sreesan Paloth |

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.