CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899714
Transaction Date	28 Oct 2026, 15:00:55
Site Name	840 - Emirates Auctions
Transaction Number	39884797 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1N4BL4BVXK*******
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2019
Color	Blue
Mileage	216156 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE ,REAR LEFT SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	LEFT BOTH REPAINTED PORTION REPAIRED REFITED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN ,SCRATCHES	دعامية
01.G Bonnet	REFITTED REPAINTED	غطاء المحرك
01.H Pillars	LEFT SIDE DOOR PILLARS ROCKER PANEL REPAIRED.	القوائم
01.I Sign of front accident	BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident	LEFT SIDE RUNNING BOARD ,ROCKER PANEL WHEEL ARCH ROOF RAIL REPAIRED.	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASIS APRON JOINT AREA SLIGHTLY DETACHED PORTIONCRACKED CHASISS COVERED ,CHECKED ONLY VISIBLE AREA .	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
02.C Chassis Number	VIN STICKER REFITTED .	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR SHAKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	MINOR JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT.	الاطار الخلفي
06 Lights		**الاضاءة**
06.A Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		**الفرامل**
07.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	MINOR LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Interior Condition		**الحاله الداخليه**
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
09.B AC Condition	OK	المكيف
09.C Air Bag	OPEN REFITTED .	وسائد هوائية
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae