

Queue Number 2826853

Transaction Date 02 Oct 2026, 11:51:01

Site Name
840 - Emirates AuctionsTransaction Number
15262310 (CC10010) (CC10010)

Vehicle Details

Chassis Number	SAJAA72D74*****
Specification	GCC Specification
Make	Jaguar
Model	XJ 6
Model Year	2004
Color	--
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA ,	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED/.	دعامية
01.E Bonnet	COMPARTMENT FIREWALL COVER ASSEMBLY ,PARTS MISSING.	غطاء المحرك
01.F Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED,DENT .	وجود مؤشر لحادث في الخلف
01.G Vehicle Color	BLUE.	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED OILY MUDDY ,PORTION DENT CHECKED ONLY VISIBLE AREA .	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,PARTS MISSING.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY LOOSE PORTION DAMAGED.	حالة المقاعد
---------------------	------------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	EXPIRED DAMAGED. .	الاطار الامامي
06.B Rear Tyre	EXPIRED DAMAGED.	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	ASSEMBLY MISSING.	ازرع المساحات والشفرة
08 Lights		الاضاءة
08.A Head Light	LENS FADED ,ALL LIGHT NOT CHECEKD .	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK ,WEAK ,BODY LEVEL LOW.	ممتص الصدمات
10.B Arms	BUSHES CUT .	ازرع
11 Steering Condition		المقود
11.A Steering Oil	OIL LEAK .	زيت المقود
11.B Steering Boot	CUT .	ربلة المقود
11.C Steering Box	OIL LEAK .	جهاز المقود
12 Interior Condition		الحالة الداخليه
12.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
12.B Mirror	LOOSE ,FADED .	المرايا
12.C AC Condition	NOT CHECKED, GRILL PORTION LOOSE.	المكيف
12.D Floor Matting	CENTER CONSOLE ASSEMBLY LOOSE.	فرش الأرضيه
12.E Dash Board	DAMAGED ,PARTS MISSING.	لوحة القيادة
12.F Roof Ceiling	PORTION LOOSE/	بطانه السقف
12.G Odometer reading	NOT CHECKED.	قراءة عداد المسافات
12.H Door Panel	WORN OUT DAMAGED PARTS MISSING.	لوحة بطانة الباب
12.I Steering Wheel and control buttons	WORN OUT PARTS MISSING LOOSE	عجلة القيادة وازرار التحكم
12.J Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae