



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **24 Nov 2021, 18:40:26**
 Transaction Number **59423551 (CC10006)** Queue Number **312309**



Chassis Number **JN8BY15Y7XX425727**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Patrol**
 Model Year **1999**
 Color **White**
 Mileage **355351 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT

REMARKS

01 Tires and Rims Condition

الاطارات

01.A Front Tyre	BOTH SIDE 2013 CRACKED & EXPIRED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2013 CRACKED & EXPIRED	الاطار الخلفي
01.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
01.D Spare Tire & Tools	TOOLS MISSING	الاطار الاحتياطي و العدة

02 Body

جسم المركبة

02.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
02.B Paint	BODY TOTALLY REPAINTED, PORTION REPAIRED, EXCEPT ROOF & BODY MINOR DENT, SCRATCHES	الصبغ
02.C Doors	PORTION REPAIRED & REPAINTED	أبواب
02.D Bumper	REPAINTED	دعامية
02.E Bonnet	PORTION REPAIRED, REPAINTED & SHOCK WEAK	غطاء المحرك
02.F Roof	RIGHT SIDE ROOF RAIL REPAINTED & PORTION REPAIRED	السقف
02.G Pillars	RIGHT SIDE A/PILLAR, POST REPAIRED	القوائم
02.H Trunk	PORTION REPAIRED & REPAINTED	صندوق
02.I Rusty	UNDER BODY PARTS, SUSPENSION, CHASSIS FRAME, FLOOR GETTING RUSTY	صدأ
02.J Floor	REAR LEFT SIDE WHEEL ARCH RUSTY, WEAK & PORTION	الارضية

DEFECT	REMARKS	
	DAMAGED	
02.K Other	FRONT FENDER FRAME ,BULK HEAD,RADIATOR SUPPORT REPAIRED	اخرى
03 Engine Condition		المحرك
03.A Engine Condition	OIL LEAK & ABNORMAL NOISY	حالة المحرك
04 Interior Condition		الحالة الداخلية
04.A AC Condition	OK	المكيف
04.B Power Window Switch	FRONT RIGHT SIDE CONTROL NOT WORKING PROPERLY	مفتاح النافذه
04.C Mirror	SWITCH BUTTON NOT WORKING	المرآيا
04.D Dash Board	CENTER COVER LOOSED	لوحة القيادة
05 Seats Condition		المقاعد
05.A Seat Condition	REAR RIGHT SIDE HEAD REST MISSING & LAST REAR NOT FIX PROPERLY	حالة المقاعد
06 Chassis Condition		الشاسي
06.A Chassis	CHASSIS FRAME RUSTY	الشاسيه
06.B Chassis Number	VIN NUMBER RUSTY	رقم القاعدة
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B DIFFERENTIAL	4WD OIL LEAK	الدفرنشل
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
09 Steering Condition		المقود
09.A Steering Box	LEFT SIDE ROMANO LEAKING	جهاز المقود
09.B Steering Mount	SIGN OF LEAK	كرسي المقود
09.C Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
10 Brake Condition		الفرامل
10.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
11 Wipers and Arms		المساحات
11.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



X FAILED

Plate Details :	O 6275 Dubai Private
Chassis No :	JN8BY15Y7XX425727
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	355356 Kms.
Origin :	Japan
Model Year :	1999
Gear Type :	--
Engine Size :	4500 CC
Engine No :	TB45/O27737
Horse Power :	--
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	7
G. V. W. :	2800 Kgs.
Empty Weight :	1800 Kgs.

Retest can be done only in Dubai

Certificate Number :	5-TAS-2021-15556768
Inspection Date :	28-11-2021
Certificate Print Date :	28-11-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	14 min 53 sec
Appointment Ref Number :	--
Start Time :	13:45
End Time :	14:00
Lane :	03
Token No. :	163
Attempt :	1
Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
14 %	14 %	11 %	2.03 %
Vehicle on Petrol HC Reading			
71 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Tire change all tires cracks & old 2013	Cracked	Major
Stop lamps fix both side brake light not working	Bulb busted	Major
Axles repair front both side axle oil seal leaking	Others (Major)	Major

Inspection Remarks:

FENDER AND FENDER FRAME, QUARTER PANEL, WHEEL ARCH RUSTY, FRONT RHS DOOR POST RUSTY REPAIRED,, CHASSIS AND UNDER BODY COMPONENTS GETTING RUSTY. MINOR BODY DENTS AND SCRATCHES. //AS PER CUSTOMER REQUEST

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460	Cash	15556768	AED 170 Collected on 28/11/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصراً في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

