CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2906085 |
| Transaction Date | 29 Oct 2026, 16:06:40 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 85515175 (CC10026) (CC10026) |




## Vehicle Details

| | |
|---|---|
| Chassis Number | 6T1BF4FK6F******* |
| Specification | GCC Specification |
| Make | Toyota |
| Model | Camry |
| Model Year | 2015 |
| Color | White |
| Mileage | N/A Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | **جسم المركبة** |
| 01.A Paint | BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY | الصبغ |
| 01.B Rusty | UNDER BODY PARTS ,SUSPENSION GETTING RUSTY | صدأ |
| 01.C Floor | UNDER FLOOR THICK RUST PROOFED PORTION DENTS, MUDDY | الارضية |
| 01.D Bumper | MISALIGN , PORTION DAMAGE | دعامية |
| 01.E Bonnet | REPAINTED PORTION REPAIRED | غطاء المحرك |
| 01.F Trunk | REPAINTED PORTION REPAIRED , MISALIGN | صندوق |
| 01.G Sign of front accident | BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED | وجود مؤشر لحادث في المقدمة |
| **02 Chassis Condition** | | **الشاصي** |
| 02.A Chassis | FRONT BOTH SIDE CHASSIS END DENT & RIGHT SIDE CHASSIS OUTER SKIRT SLIGHTLY DETOUCH | الشاسيه |
| **03 Engine Condition** | | **المحرك** |
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED PARTS REFITTED GETTING RUSTY | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | **الجير** |
| 04.A Gear Box Visual Condition | NOT CHECKED PARTS REFITTED GETTING RUSTY | الحالة النظريه للجير |
| 04.B Road Test | NOT CHECK | فحص علي الطريق |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Tires and Rims Condition** | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2026 | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2023 CRACK | الاطار الخلفي |
| 05.C Rims Condition | MINOR DENT SCRATCHES | حالة الجنوط |
| **06 Lights** | | الاضاءة |
| 06.A Head Light | ALL LIGHTS NOT CHECKED | الاضاءة الرئيسية |
| **07 Suspension System** | | ممتص الصدمات |
| 07.A Arms | BUSHES CRACK | ازرع |
| 07.B Stabilizer Bar And Link Rod | BOOT CRACK | عمود التوازن و مثبت عمود التوازن |
| **08 Interior Condition** | | الحاله الداخليه |
| 08.A Other | CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED | اخري |
| 08.B Mirror | CENTER VIEW MIRROR DAMAGE | المرايا |
| 08.C AC Condition | NOT CHECK | المكيف |
| 08.D Audio | LCD SCREEN BADLY CRACK | صوتيات |
| 08.E Roof Ceiling | PORTION WORN OUT | بطانه السقف |
| 08.F Sun Visor | RIGHT SIDE DAMAGE | حاجب الشمس |
| 08.G Steering Wheel and control buttons | PORTION WORN OUT | عجلة القيادة وازرار التحكم |
| 08.H Gear Shifting Lever | PORTION WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**