



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Jan 2023, 15:52:42
Transaction Number	78875254 (CC10010)	Queue Number	657792



Chassis Number	JTHCH96S760011362
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	GS 300
Model Year	2006
Color	Black
Mileage	273301 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020 CRACKED ,	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018/2019 CRACKED,	الاطار الخلفي
01.C Rims Condition	RIMS MINOR DENT ,SCRATCHES	حالة الجنوط
02 Body		جسم المركبة
02.A Bumper	MISALIGN,PORTION DAMAGED	دعامية
02.B Other	FRONT FENDER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED	اخرى
02.C Sign of front accident		وجود مؤشر لحادث في المقدمة
02.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
02.E Doors	FRONT LEFT SIDE SKIRT MISSING	أبواب
02.F Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
02.G Floor	UNDER FLOOR COVERED, CHECKED ONLY VISIBLE AREA.	الارضية
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	NOT CHECK,OIL LEAK REFITTED	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
04 Chassis Condition		الشاصي
04.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED	الشاسيه
05 Interior Condition		الحاله الداخليه
05.A Sunroof	MISALIGN	فتحت سقف
05.B AC Condition	NOT CHECK	المكيف
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,OIL LEAK,REFITTED	حالة المحرك النظري
07 Seats Condition		المقاعد
07.A Seat Condition	PORTION DAMAGED	حالة المقاعد
08 Lights		الاضاءة
08.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
09 Steering Condition		المقود
09.A Axle	BOOT CUT,LEAKING	اكسلات
10 Suspension System		ممتص الصدمات
10.A Ball Joint	BOOT CUT	مفصل كروي
10.B Shock Absorber	LEAK	ممتص الصدمات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.