

## **TEST CERTIFICATE**

Site Number Transaction Number **840-Emirates Auctions** 83578404 (CC10006)

Transaction Date

07 Aug 2022, 16:48:52

Queue Number 312309

Chassis Number

1GKS27EF6CR300378

**GMC** 

**Engine Number** 

Manufacturer

Vehicle Class Car

Model Yukon

Model Year 2012

White Color

356390 Km Mileage

Fuel Type **Petrol** 

No. Of Cylinders

**GCC** Specification Specification



**REMARKS** 

| O1 Body      |  | جسم المركبة |
|--------------|--|-------------|
| 01.A Paint   | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY     | الصبغ       |
| 01.B Fenders | RIGHT SIDE BOTH REPAIRED, REPAINTED                        | مدكار       |
| 01.C Doors   | RIGHT SIDE BOTH REPAIRED, REPAINTED                        | أبواب       |
| 01.D Bumper  | MISALIGN   | دعامية      |
| 01.E Rusty   | UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY | صدأ         |

| 02 Interior Condition | الحاله الداخليه |
|-----------------------|-----------------|

| 02.A Dash Board   | CRACKED | لوحة القياده |
|-------------------|---------|--------------|
| 02.B AC Condition | OK      | المكيف       |

## **03 Engine Condition** المحرك

| 03.A Visual Engine Condition | OK | حالة المحرك النظرى |
|------------------------------|----|--------------------|
|------------------------------|----|--------------------|

## **04 Transmission Condition** الجير NOT OUTOK

| 04.A Road Test       | NOT CHECK | فحص علي الطريق    |
|----------------------|-----------|-------------------|
| 04.B Visual Gear Box | OK        | حالة الجير النظرى |
| Condition            |           |                   |

| DEFECT                      | REMARKS  |                |
|-----------------------------|--|----------------|
| 04.C DIFFERENTIAL           | FRONT OIL LEAK                                       | الدفرنشل       |
| O5 Lights                   |  | الاضاءة        |
| 05.A Warning Light          | WARNING LIGHT ON IN DISPLAY                          | ضوء تحذير      |
| 06 Battery Condition        |  | حالة البطارية  |
| 06.A Battery bracket        | MISSING  | حامل البطارية  |
| 07 Chassis Condition        |  | الشاصي         |
| 07.A Chassis                | CHASSIS FRAME COMPLETLY RUST PROOFED & PORTION RUSTY | الشاسيه        |
| 08 Tires and Rims Condition |  | الاطارات       |
| 08.A Front Tyre             | BOTH SIDE 2022                                       | الاطار الامامي |
| 08.B Rear Tyre              | BOTH SIDE 2022                                       | الاطار الخلفي  |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.