



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 19883756 | Plate Category | : PRIVATE |
| Transaction Date | : 02 JUN 2020 10:36:28 | Plate Number | : A299761 EA |
| Queue Number | : 181048 | Import Doc. Ref. | : |
| Chassis Number | : SALLMAM549A299761 | Manufacturer/Model | : RANGEROVER/HSE |
| Engine Number | : | Model Year | : 2009 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : SILVER |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|--------|------------------------------|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| VISUAL TEST: | | |
| 02 Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 02.13 - Stub Axle Assemblies, Boots | | المحور |
| 02.15 - Suspension Crack Or Bend, Bushes | | التوصيلات |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | | الاطارات الامامية |
| 05 Body | | الهيكل |
| 05.02 - Paint | | الصبغ |
| 05.05 - Bumpers | | الدعامية |
| 06 General Items | | الاشياء العامة |
| 06.01 - Wiper Blades | | ماسحات الزجاج الامامي |
| 06.13 - Exhaust System | | نظام العادم |
| 06.16 - Engine Condition, Smoke | | حالة المحرك - الدخان |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | OK | الشاصي جيد |
| 09.09 - Engine And Gear Box Performance Ok | OK | فحص حالة الماكينة والجير |
| 09.25 - Body Repainted | | أثر صبغ في المركبة |

The Test Certificate Shows the test Result at the time of inspection only.