CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2946443
Transaction Date	09 Nov 2026, 15:17:32
Site Name	840 - Emirates Auctions
Transaction Number	38514464 (CC10021) (CC10021)



Vehicle Details

Chassis Number	JN1CC13CX8*******
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2008
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Sign of front accident	BUMPER FRAME FENDER FRAME RADIATOR FRAME SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL,QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis Extension	REAR EXTENSION END REPAIRED	تمديدات الشاسي
02.B Chassis	FRONT CHASSIS END REPAIRED	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	PORTION CRACK	لوحة القياده
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae