



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>18 Jul 2022, 16:19:25</b>
Transaction Number	<b>33056578 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN8FY15Y73X504469</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>2003</b>
Color	<b>White</b>
Mileage	<b>337809 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	NOT CHECK, REFITTED	حالة الجير النظرى
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Odometer reading	NOT CHECK	قراءة عداد المسافات
02.B AC Condition	NOT CHECK	المكيف
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	BODY TOTALY REPAINTED, PORTION REPAIRED EXCEPT ROOF & DENTS, SCRATCHES ,PORTION FADED, RUSTY ON BODY	الصبغ
03.B Bonnet	STAND MISSING	غطاء المحرك
03.C Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT, WHEEL ARCH REPAIRED	اخرى
03.D Sign of back accident		وجود مؤشر لحادث في الخلف
03.E Sign of front accident		وجود مؤشر لحادث في المقدمة
03.F Rusty	UNDER BODY PARTS, SUSPENSION ,CHASSIS ,FLOOR GETTING RUSTY	صدأ

DEFECT	REMARKS	
03.G Floor	REAR BACK PANEL , QUATER PANEL, WHEEL ARCH REPAIRED	الارضية
<b>04 Suspension System</b>		ممتص الصدمات
04.A Arms	BOTH SIDE LOWER ARM REAR CONTROL ARM BUSHES CRACKED	ازرع
<b>05 Tires and Rims Condition</b>		الاطارات
05.A Front Tyre	BOTH SIDE 2020 WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>06 Steering Condition</b>		المقود
06.A Steering Box	BOTH SIDE ROMANO LEAKING	جهاز المقود
06.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>07 Engine Condition</b>		المحرك
07.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK & OIL LEAK & REFITTED	حالة المحرك النظري
<b>08 Chassis Condition</b>		الشاسي
08.A Chassis	FRONT BOTH SIDE CHASSIS ,REAR LEFT SIDE CROSS MEMBER REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.