



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 Aug 2022, 11:11:30</b>
Transaction Number	<b>97511516 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>MHFYX59G0D8044989</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Fortuner</b>
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>179351 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK	حالة المحرك النظرى
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	NOT CHECK & OIL LEAK	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	NOT CHECK	المكيف
03.B Odometer reading	NOT CHECK	قراءة عداد المسافات
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Floor	UNDER BODY COMPLETE RUSTPROOFED .	الارضية
04.B Paint	BODY TOTALY REPAINTED EXCEPT ROOF & PORTION REPAIRED, MINOR DENT,SCRATCHES	الصبغ
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Steering Oil	OIL LEAK	زيت المقود
<b>06 Chassis Condition</b>		<b>الشاصي</b>

DEFECT	REMARKS	
06.A Chassis	COMPLETE CHASSIS THICK RUSTPROOFED VISIBLE AREA OK .	الشاسيه
<b>07 Tires and Rims Condition</b>		الاطارات
07.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
<b>08 Wipers and Arms</b>		المساحات
08.A Wiper Arm &Blade	REAR MISSING	ازرع المساحات والشفرات
<b>09 Lights</b>		الاضاءة
09.A Other	NOT CHECKED ,	اخرى
<b>10 Suspension System</b>		ممتص الصدمات
10.A Arms	BUSHES CRACKED .	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.