



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 May 2023, 11:13:11
Transaction Number	82094164 (CC10008)	Queue Number	726306



Chassis Number	1GYFK13209R164911
Engine Number	
Vehicle Class	Car
Manufacturer	Cadillac
Model	Escalade
Model Year	2009
Color	White
Mileage	298136 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition المحرك		
01.A Visual Engine Condition	OIL LEAK,REFITTED,OVER HEAT	حالة المحرك النظري
01.B Mount	MOUNT BUSHES CRACKED	كرسي
01.C Smoke	WHITE SMOKE	دخان
02 Lights الاضاءة		
02.A Head Light	LENS FADED	الاضاءة الرئيسية
03 Steering Condition المقود		
03.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
03.B Axle	BOOT CUT	اكسلات
04 Suspension System ممتص الصدمات		
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
05 Body جسم المركبة		
05.A Fenders	FRONT BOTH SIDE PORTION REPAINTED,FADED & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
05.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED,PORTION GETTING	الصبغ

DEFECT	REMARKS	
	RUSTY	
05.C Doors	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	أبواب
05.D Bumper	MISALIGN,PORTION DAMAGED	دعامية
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	MINOR OIL LEAK,REFITTED,JERKING	حالة الجير النظرى
06.B Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Chassis Condition		الشاصي
07.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
08 Interior Condition		الحاله الداخليه
08.A AC Condition	NOT COOLING	المكيف
08.B Mirror	LEFT SIDE AUTO FOLDING NOT WORKING	المرايا
08.C Other	CENTER CONSOLE BOX COVER PORTION DAMAGED	اخرى
09 Tires and Rims Condition		الاطارات
09.A Rear Tyre	BOTH SIDE 2018,CRACKED	الاطار الخلفي
09.B Front Tyre	BOTH SIDE 2018,CRACKED	الاطار الامامي
10 Seats Condition		المقاعد
10.A Seat Condition	PORTION DAMAGED	حالة المقاعد
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	COOLANT LEAK	خزان التبريد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.