CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2923253
Transaction Date	29 Oct 2026, 13:22:47
Site Name	840 - Emirates Auctions
Transaction Number	94710403 (CC10026) (CC10006)



Vehicle Details

Chassis Number	JN6FE54SX2*******
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2002
Color	White
Mileage	709882 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY , REAR BUMPER FRAME PORTION DENT	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DAMAGE , REAR SEAT MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHUST PIPE CUT REWELDED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08.B Tail Light	RIGHT SIDE DAMAGE	الضوء الخلفي
08.C Indicator & Hazard light	FRONT RIGHT SIDE INDICATOR HOUSING DAMAGE	الاشارات
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C FLoor Matting	DIRTY	فرش الأرضيه
11.D Dash Board	PORTION WORN OUT	لوحة القياده
11.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.F Sun Visor	BOTH SIDE DAMAGE	حاجب الشمس
11.G Door Panel	PORTION DAMAGE	لوحة بطانة الباب
11.H Steering Wheel and control buttons	DAMAGE	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae