CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2993840
Transaction Date	16 Nov 2026, 15:08:39
Site Name	840 - Emirates Auctions
Transaction Number	35523038 (CC10009) (CC10019)



Vehicle Details

Chassis Number	MR0FX22G7A*******
Specification	GCC Specification
Make	Toyota
Model	Hilux
Model Year	2010
Color	Unknown
Mileage	904540 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY CHASSIS SUSPENSION RUSTY	صدأ
01.D Bumper	MISALIGN,GRILL PORTION DAMAGED,LOGO MISSING	دعامية
01.E Bonnet	REFITTED,HANDLE LOCK DAMAGED	غطاء المحرك
01.F Door Handle &Lock	FRONT RIGHT SIDE HANDLE LOCK COVER MISSING	مقابض الأبواب والأقفال
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Vehicle Color	WHITE	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME RUSTY / RIGHT SIDE CHASSIS RUSTY HOLE CRACKED, PORTION RUSTY REPAIRED,PORTION DENT	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OPEN REFITTED BOLTS MISSING GETTING RUSTY, SHAING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OPEN REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Lights		**الاضاءة**
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		**ممتص الصدمات**
08.A Arms	BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		**الحاله الداخليه**
09.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
09.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING	المرايا
09.C AC Condition	NOT WORKING	المكيف
09.D Dash Board	PORTION DAMAGED	لوحة القياده
09.E Sun Visor	LEFT SIDE PORTION LOOSE	حاجب الشمس
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT,HORN NOT WORKING	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	DUST COVER PORTION DAMAGED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae