CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941231
Transaction Date	04 Nov 2026, 14:24:02
Site Name	840 - Emirates Auctions
Transaction Number	97183601 (CC10013) (CC10013)



Vehicle Details

Chassis Number	5KBRL5822C*******
Specification	GCC Specification
Make	Honda
Model	Odyssey
Model Year	2012
Color	Silver
Mileage	310428 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Doors	FRONT LEFT NOT OPEN FROM OUT SIDE	أبواب
01.C Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN, PORTION CRACK	دعامية
01.F Door Handle &Lock	FRONT LEFT LOCK MISSING	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED DIRTY , MUDDY , PARTS GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT CRACK / SAFETY COVER CRACK	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	MINOR JERKING REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2021 EXPIRED CRACKED	الاطار الامامي
07.B Rear Tyre	2021 EXPIRED CRACKED	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	LOWER ARM BUSHES CUT	ازرع
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
11.B AC Condition	NOT WORKING	المكيف
11.C Power Window Switch And Glass	REAR RIGHT SIDE GLASS NOT WORKING	مفتاح النافذه و الزجاج
11.D Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القياده
11.E Door Panel	PORTION WORN OUT CRACK	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae