

Queue Number 2818727

Transaction Date 30 Sep 2026, 14:38:55

Site Name
840 - Emirates AuctionsTransaction Number
22563183 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WBAFR7107D*****
Specification	GCC Specification
Make	BMW
Model	535 i
Model Year	2013
Color	Unknown
Mileage	304544 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY MINOR DENTS SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COMPLETELY COVERED DIRTY OILY	الارضية
01.D Bumper	MISALIGN , MINOR SCRATCHES PORTION FADED	دعامية
01.E Windshield	SPOT DENT	زجاج
01.F Roof	STRIP PART MISSING	السقف
01.G Trunk	REAR LOGO FADED	صندوق
01.H Vehicle Color	BLACK	لون المركبة

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FULLY COVERED OILY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخرى

03 Engine Condition المحرك

03.A Engine Visual Condition	OIL LEAK DRIPPING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION DAMAGE , BACK COVER LOOSE	حالة المقاعد
---------------------	-----------------------------------	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES / HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	MAIN SWITCH MELTED	الاضاءة الرئيسية
07.B Tail Light	BOTH SIDE LOOSE , RIGHT SIDE NOT WORKING CRACK	الضوء الخلفي
07.C Fog light	BOTH SIDE LEN FADED	كشاف الضباب
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH PORTION SIGN OF CRACK	فرامل اليد
08.B Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	FRONT RIGHT LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	ازرع
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخلية
11.A Other	CENTER CONSOLE BOX COVER WORN OUT	اخرى
11.B Mirror	LEFT SIDE AUTO FOLDING NOT WORKING	المرآيا
11.C AC Condition	OK , FRONT GRILL PORTION CRACK & REAR GRILL & ADJUSTABLE SWITCH DAMAGE	المكيف
11.D Power Window Switch And Glass	MAIN SWITCH PANEL , REAR BOTH SIDE , FRONT RIGHT SIDE PORTION MELTED	مفتاح النافذه و الزجاج
11.E Audio	LCD SCREEN PORTION FADED	صوتيات
11.F Dash Board	PORTION WORN OUT , CONTROL PANEL SWITCH FADED	لوحة القيادة
11.G Roof Ceiling	PORTION DAMAGE	بطانه السقف
11.H Door Panel	LEATHER PORTION LOOSE , GRAB HANDLE MELTED	لوحة بطانة الباب
11.I Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB PORTION WORN OUT , CONTROL BUTTON GETTING FADED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae