



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 May 2022, 17:24:31
Transaction Number	27927698 (CC10006)	Queue Number	312309



Chassis Number	1GTPKVEOXAZ228731
Engine Number	
Vehicle Class	Heavy
Manufacturer	GMC
Model	Sierra
Model Year	2010
Color	Black
Mileage	167216 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Dash Board	DAMAGED CRACKED	لوحة القيادة
01.B AC Condition	OK	المكيف
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
03 Transmission Condition		الجير
03.A Road Test	NOT CHECKED	فحص علي الطريق
03.B Visual Gear Box Condition	JERKING, MINOR OIL LEAK REFITTED	حالة الجير النظرى
03.C Gear Box Mount	MOUNT RUBBER MINOR CRACKED	كرسي الجير
04 Body		جسم المركبة
04.A Paint	BODY REPAINTED , PORTION REPAIRED , MINOR DENTS SCRATCHES	الصبغ
04.B Fenders	REPAINTED , PORTION REPAIRED	مدكار
04.C Doors	REPAINTED	أبواب
04.D Floor	UNDER FLOR BODY CHASSIS FRAME & SUSPENSION	الارضية

DEFECT	REMARKS	
	PARTS RUST PROOFED	
04.E Bonnet	REPAINTED	غطاء المحرك
04.F Roof	REPAINTED	السقف
05 Engine Condition		المحرك
05.A Mount	MOUNT RUBBER CRACKED	كرسي
05.B Visual Engine Condition	MINOR OIL LEAK , REFITTED , SHAKING	حالة المحرك النظري
05.C Smoke	WHITE SMOKE	دخان
06 Exhaust System		نظام العادم
06.A Modification	HAVE HEADRESS, CATALYTIC CONVERTER REMOVED	تعديلات
07 Suspension System		ممتص الصدمات
07.A Arms	FRONT CONTROL ARM BUSHES CRACKED	ازرع
07.B Leaf Spring	BUSHES WORN OUT	
07.C Ball Joint	BOOT CUT	مفصل كروي
07.D Shock Absorber	REAR LEAK	ممتص الصدمات
08 Chassis Condition		الشاسي
08.A Chassis	CHASSIS FRAME TOATLLY HARD THICK RUST PROOFED , FRONT RIGHT SIDE HOEL AREA MINOR DENT	الشاسيه
08.B Chassis Number	(VIN) CHECKED ON LEFT SIDE DOOR ONLY ,CLEAN PUNCHING NUMBER FOR RECHECK	رقم القاعدة
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Transfer Certificate :	66430675
Chassis No :	1GTPKVE0XAZ228731
Vehicle Make :	GMC
Vehicle Model :	SIERRA
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	167219 Kms. x
Previous Odometer Reading :	363433 Kms.
Origin : United States	Model Year : 2010
Gear Type : Automatic	Engine Size : 6600 CC
Engine No : NIL	Horse Power : 315
Axles No : 2	Cylinders : 8
No Of Doors : 2	No Of Seats : 3
G. V. W. : 2800 Kgs.	Empty Weight : 2299 Kgs.

Certificate Number :	5-TAS-2022-16737004
Inspection Date :	10-05-2022
Certificate Print Date :	10-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 13 sec
Appointment Ref Number :	--
Start Time : 14:19	End Time : 14:28
Lane : 02	Token No. : 199
Attempt : 1	Prints No : 1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)

126856 KM	13054 L	21148 AED	31.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 5 %	Parking brake imbalance between LHS and RHS 0 %	Vehicle on Petrol CO Reading 0.28 %
Vehicle on Petrol HC Reading 36 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks: FRONT CHASSIS END MINOR DENT. CHASSIS THICK RUST PROOFED, EXHAUST SYSTEM MODIFIED,, OLD //



Odometer Record
Replace Events Date

10/05/2022

Payment Details

Inspection Performed by 71051	Payment Method Cash	Transaction Number 16737004	Service Fees AED 170 Collected on 10/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

