CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2949337
Transaction Date	07 Nov 2026, 12:41:16
Site Name	840 - Emirates Auctions
Transaction Number	19107116 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KNAGM4AD9C*******
Specification	Imported
Make	Kia
Model	Optima
Model Year	2012
Color	White
Mileage	184537 Miles
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT REFITTED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Bumper	MISALIGN ,SCRATCHES .PORTION CUT	دعامية
01.F Roof	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	السقف
01.G Bonnet	REPAINTED PORTION REPAIRED.	غطاء المحرك
01.H Sign of front accident	FRONT ASSEMBLY REFITTED.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LRIGHT SIDE CHASSIS LOERT SKIRT BEND SLIGHTLY DETACHED , CHASSIS COVERED ,CHECKED ONLY VISIBLE AREA .	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED .	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
05.D Spare Tire &Tools	RIM MISSING	الاطار الاحتياطي و العدة
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT/WARNING MESSAGE ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED. .	ازرع
09 Steering Condition		المقود
09.A Tie Rod	RIGHT SIDE TIE ROD BEND	رودات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY.	اخري
10.B AC Condition	NOT COOLING	المكيف
10.C Sun Visor	LOOSE	حاجب الشمس
10.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae