



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Apr 2022, 10:31:12
Transaction Number	52422262 (CC10008)	Queue Number	312309



Chassis Number	JT8BD69S430177092
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	GS 300
Model Year	2003
Color	White
Mileage	228231 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Other	FRONT SUSPENSION NOISY WHILE DRIVING ,TURNING	اخرى
01.B Arms	FRONT LOWER ARM BUSHES & CONTROL BUSHES CRACKED	ازرع
02 Battery Condition		حالة البطارية
02.A Battery bracket	MISSING	حامل البطارية
03 Body		جسم المركبة
03.A Paint	BODY REPAINTED EXCEPT ROOF,REPAIRED, DENT,SCRATCHES & PORTION RUSTY	الصبغ
03.B Roof	PORTION RUSTY	السقف
03.C Bonnet	SHOCK WEAK	غطاء المحرك
03.D Other	REAR COMPARTMENT ,BACK PANEL QUATER PANEL ,TRUNK COMPARTMENT PANEL REPAIRED	اخرى
03.E Pillars	BOTH SIDE C/PILLAR ,ROCKER PANEL CUT REPAIRED	القوائم
03.F Floor	FLOOR MINOR DENT	الارضية
03.G Fenders	REAR BOTH SIDE FENDER REPLACED	مدكار
04 Interior Condition		الحاله الداخليه

DEFECT	REMARKS	
04.A AC Condition	OK	المكيف
04.B Mirror	RIGHT SIDE MIRROR DAMAGED, GLASS MISSING	المرآيا
04.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظرى
05.C Gear Box Mount	BOOT CUT	كرسي الجير
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2018/2019 CRACKED	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2018/2015 & EXPIRED CRACKED	الاطار الامامي
07 Engine Condition		المحرك
07.A Smoke	WHITE SMOKE	دخان
08 Chassis Condition		الشاسي
08.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Change possession :	66415403
Chassis No :	JT8BD69S430177092
Vehicle Make :	LEXUS
Vehicle Model :	GS 300
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	228232 Kms. x
Previous Odometer Reading :	339861 Kms.
Origin : Japan	Model Year : 2003
Gear Type : Automatic	Engine Size : 5000 CC
Engine No : NIL	Horse Power : 245
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 5
G. V. W. : 1450 Kgs.	Empty Weight : 1000 Kgs.

Certificate Number :	5-MUT-2022-16678699
Inspection Date :	26-04-2022
Certificate Print Date :	26-04-2022
Services :	Registration Test
Vehicle Testing Partner :	Al Mutakamela Vehicle Testing LLC
Vehicle Testing Center :	Al Mutakamela Vehicle Testing Alaweer
Total Time Taken :	9 min 20 sec
Appointment Ref Number :	--
Start Time : 23:26	End Time : 23:36
Lane : 02	Token No. : 294
Attempt : 1	Prints No : 1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)

51675 KM	5318 L	8616 AED	12.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 2 %	Parking brake imbalance between LHS and RHS 7 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 26 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5000	3000	
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks:

REAR CHASSIS/CHASSIS EXTENSIONS REPAIRED HAVE CCM REPORT#104057. REAR COMPARTMENT PANEL,REAR QUARTER PANEL,SPARE WHEEL-HOUSING,C PILLARS OLD REPAIRED. FLOOR HAVE MINOR DENTS.



Odometer Record

Replace Events Date

26/04/2022

Payment Details

Inspection Performed by 0686	Payment Method Cash	Transaction Number 16678699	Service Fees AED 170 Collected on 26/04/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Khawlah Abdo Saleh Moshen

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.