

Queue Number

2508592

Transaction Date

03 Jul 2026, 16:58:42

Site Name

840 - Emirates Auctions

Transaction Number

73893592 (CC10013) (CC10012)



Vehicle Details

Chassis Number	KL1JD7D53E*****
Specification	GCC Specification
Make	Chevrolet
Model	Trax LT
Model Year	2014
Color	Brown
Mileage	199082 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUST PROOFED MINOR DENT MUDDY DIRTY	الارضية
01.D Bumper	MISALIGN , SCRATCHES	دعامية
01.E Vehicle Color	GRAY	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	MINOR OI LEAK , MUDDY , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER PORTION CUT	حالة المقاعد
---------------------	-------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR OIL LEAK , PARTS GETTING RUSTY , MUDDY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2021 BOTH SIDE DRY CRACK	الاطار الامامي
06.B Rear Tyre	2021 BOTH SIDE DRY CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10.B Axle	BOOT CUT	اكسلات
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
11.B Mirror	CENTER MIRROR PORTION LOOSE MINOR FADED	المرآيا
11.C AC Condition	OK	المكيف
11.D Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH MAN NOT WORKING PROPERLY , SWITCH LOCK COVER MISSING	مفتاح النافذه و الزجاج
11.E Audio	SCREEN FADED	صوتيات
11.F Sun Visor	LEFT SIDE COVER MIRROR MISSING	حاجب الشمس
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	LOCK COVER MISSING , COVER PANEL PORTION CRACK	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير

station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae