

Queue Number

2899774

Transaction Date

24 Oct 2026, 11:35:37

Site Name

840 - Emirates Auctions

Transaction Number

81676725 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WB6JU0A06L*****
Specification	GCC Specification
Make	BMW
Model	X5
Model Year	2020
Color	Green
Mileage	37382 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY STICKERING , PAINT NOT CHECKED MINOR SCRATCHES . STICKERING PORTION CUT LOOSE	الصبغ
01.B Rusty	UNDER FLOOR PARTS POWERTRAIN RUNNING PARTS ,SUSPENSION PARTS GETTING RUSTY ,SIGN OF FLOODED.	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,MISDDLE FLOORING DENT,CHECKED ONLY VISIBLE AREA	الارضية
01.D Bumper	MINOR SCRATCHES .	دعامية
01.E Trunk	NOT OPEN	صندوق
01.F Fuel Tank	FUEL CANISTER DENT .	خزان الوقود
01.G Vehicle Color	GRAY STICKERS.	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED NOT VISIBLE PROPERLY , CHECKED ONLY VIISBLE REA .	الشاسية
02.B Other	NEED TO REMOVCE FRONT BOTH SIDE FENDER COVER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED ,COMPONENT PARTS GETTING RUSTY, UNDER PORTION COVERD.	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	UNDER SEAT METAL PARTS GETTING RUSTY.	حالة المقاعد
---------------------	---------------------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,COMPONENT PARTS GETTING RUSTY.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED,	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY .	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES DRY CRACKED.	ازرع
10 Interior Condition		الحاله الداخليه
10.A AC Condition	NOT CHECKED .	المكيف
10.B Engine Start Button	REMOTE KEY NOT FOUND.	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae