CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966681
Transaction Date	10 Nov 2026, 11:53:18
Site Name	840 - Emirates Auctions
Transaction Number	11084986 (CC10008) (CC10011)



Vehicle Details

Chassis Number	1C4RJFDJ8D*******
Specification	GCC Specification
Make	Jeep
Model	Grand Cherokee
Model Year	2013
Color	Black
Mileage	115248 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED,FRONT LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN	دعامية
01.F Roof	REPAINTED	السقف
01.G Trunk	LUGGAGE SHADE MISSING	صندوق
01.H Sign of side accident		وجود مؤشر لحادث في الجانب
01.I Vehicle Color	RED	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	MINOR OIL LEAK ,REFITTED PARTS GETTING RUSTY ,ABNORMAL NOISY,,SHAKING ,OIL COOLER PIPE DISCONNECTED	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT SIDE COVER CRACKED	حالة المقاعد
05 Exhaust System		**نظام العادم**

Condition	Remarks	الحالة
05.A Other	EXHAUST PIPE CUT REWELDED	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR OIL LEAK ,REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Gear Box Mount	MOUNT BUSHES CRACK	كرسي الجير
06.C Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07.C Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES MINOR CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED,CUP HOLDER PANEL PORTION WORN OUT,INTERIOR PARTS GETTING RUSTY	اخري
10.B Mirror	LEFT SIDE COVER PORTION CRACK,CENTER VIEW MIRROR ASSEMBLY COVER MISSING	المرايا
10.C AC Condition	OK,GRILL PORTION DAMAGED	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH NOT WORKING	مفتاح النافذه و الزجاج
10.E Audio	SCREEN GETTING FADED,ANTENNA DAMAGED	صوتيات
10.F Dash Board	LEATHER REFITTED	لوحة القياده
10.G Roof Ceiling	MINOR CUT	بطانه السقف
10.H Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.J Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae