

Queue Number 2706979

Transaction Date 07 Sep 2026, 13:01:39

Site Name
840 - Emirates AuctionsTransaction Number
35747403 (CC10021) (CC10021)

Vehicle Details

Chassis Number 1FMEU73E89*****
 Specification GCC Specification
 Make Ford
 Model Explorer
 Model Year 2009
 Color Blue
 Mileage N/A NA
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED	دعامية

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	CHASSIS FRAME MUDDY PORTION GETTING RUSTY,CHECKED VISIBLE ARAE ONLY / OK	الشاسية
--------------	--	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition	الجير
---------------------------	-------

04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition	الاطارات
-----------------------------	----------

05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
06.B Tail Light	DAMAGED	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		مفصص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Door Panel	WORN OUT	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae