

Queue Number	2838326	Transaction Date	06 Oct 2026, 15:01:15
Site Name	840 - Emirates Auctions	Transaction Number	30308106 (CC10009) (CC10012)



Vehicle Details

Chassis Number	LMGCS1G88K*****
Specification	GCC Specification
Make	GAC
Model	GS 7
Model Year	2019
Color	White
Mileage	127528 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION DENT,FRONT CHASSIS NOT VISIBLE	الارضية
01.E Bonnet	SHOCK WEAK NOT WORK	غطاء المحرك
01.F Trunk	PORTION REPAINTED PORTION REPAIRED	صندوق
01.G Sign of back accident	BACK PANEL RIGHT SIDE QUARTER PANELR EPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINIOR OIL EAK PARTS REFITTED	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL WET PARTS GETTING RUSTY,MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Interior Condition		الحاله الداخليه
06.A Other	INTERIOR PARTS GETTING RUSTY , CENTER CONSOLE BOX SLIDING COVER DAMAGED	اخرى
06.B Mirror	LEFT SIDE ADJUSTMENT NOT WORKING , BUTTON LOOSE	المرآيا
06.C AC Condition	OK	المكيف
06.D Gear Shifting Lever	DUST COVER CRACKED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae