CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945026
Transaction Date	07 Nov 2026, 12:40:22
Site Name	840 - Emirates Auctions
Transaction Number	38206068 (CC10026) (CC10026)



Vehicle Details

Chassis Number	YV1MS38549*******
Specification	GCC Specification
Make	Volvo
Model	S40
Model Year	2009
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	5

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PARTS THICK RUST PROOFED PORTION DENT	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE FIX BY SCREW	دعامية
01.G Bonnet	STAY SHOCK WEAK , NOT WORKING	غطاء المحرك
01.H Trunk	NOT OPENING	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS MUDDY COVERED , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION CRACK , DRIVER SEAT SIDE PANEL DAMAGE	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	NOT CHECK , PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE BADLY CRACK , WORN OUT	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LES FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX WORN OUT , INETERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
11.B Mirror	CENETR VIEW MIRROR DAMAGE	المرايا
11.C AC Condition	NOT CHECK	المكيف
11.D Dash Board	WORN OUT	لوحة القياده
11.E Roof Ceiling	WORN OUT	بطانه السقف
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae