CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945024
Transaction Date	06 Nov 2026, 10:14:55
Site Name	840 - Emirates Auctions
Transaction Number	79496445 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MHFB29F35J*******
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2018
Color	White
Mileage	229131 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR LEFT SIDE QUARTER PANEL REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED, MINOR DENTS SCRATCHES .	الصبغ
01.C Doors	FRONT BOTH SIDE ,REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDE BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT .	الارضية
01.F Bonnet	PORTION REPAINTED PORTION REPAIRED.	غطاء المحرك
01.G Sign of front accident	BULKHEAD REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL WET KSHAKING ,COMPONENT PARTS RUSTY.ENGINE OVER HEAT.	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DIRTY.	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	COMPONENT PARTS GETTING RUSTY ,GET JERKING .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018 EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT COOLING.	المكيف
10.C Door Panel	WORNO UT PORTION LOOSE	لوحة بطانة الباب
10.D Steering Wheel and control buttons	WORN OUT PORTION CUT .	عجلة القيادة وازرار التحكم
10.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae