



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Sep 2022, 10:59:35
Transaction Number	89005824 (CC10006)	Queue Number	595671



Chassis Number	WP1ZZZ92ZBLA48587
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Cayenne
Model Year	2011
Color	Black
Mileage	73569 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.C Pillars	RIGHT SIDE PILLAR OUTER PANEL PORTION REPAIRED,REPAINTED & BOTH SIDE A/PILLAR ,LEFT SIDE B PILLAR INNER COVER LOOSE	القوائم
01.D Bumper	REAR BUMPER FRAME DENT,BACK PANEL REPAIRED	دعامية
01.E Floor	UNDER FLOOR PORTION COVERED	الارضية
01.F Doors	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.G Windshield	FRONT SPOT CRACKED	زجاج
01.H Sign of back accident		وجود مؤشر لحادث في الخلف
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	REFITTED	حالة الجير النظري
02.C DIFFERENTIAL	MOUNT CRACKED	الدفرنشيل
03 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
03.A Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
03.B Front Tyre	BOTH SIDE 2019	الاطار الامامي
03.C Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
04 Suspension System		ممتص الصدمات
04.A Suspension Subframe	DENT	
04.B Arms	LOWER ARM BUSH CRACKED	ازرع
04.C Shock Absorber	FRONT MOUNT RUBBER CUT	ممتص الصدمات
04.D Ball Joint	BOOT CUT	مفصل كروي
05 Steering Condition		المقود
05.A Axle	BOOT LEAK	اكسلات
06 Interior Condition		الحالة الداخلية
06.A AC Condition	OK & WINDOW ADJUSTER PORTION DAMAGED	المكيف
06.B Steering Wheel and control buttons	HORN SWITCH MODIFIED TO FIX ADDITIONAL	عجلة القيادة وازرار التحكم
06.C Sunroof	CURTAIN NOT WORKING	فتحت سقف
06.D Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
06.E Roof Ceiling	PORTION LOOSE	بطانه السقف
07 Seats Condition		المقاعد
07.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
08 Engine Condition		المحرك
08.A Visual Engine Condition	SIGN OF OIL WET & REFITTED	حالة المحرك النظري
09 Exhaust System		نظام العادم
09.A Other	CATAYLIC CONVERTER MISSING & EXHAUST NOISY, PIPE WELDED	اخرى
10 Chassis Condition		الشاسي
10.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
11 Brake Condition		الفرامل
11.A Break Pads	WEAR LIMIT .	سقايف الرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

