



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **08 Mar 2023, 14:02:24**  
 Transaction Number **58260392 (CC10006)** Queue Number **685129**



Chassis Number **JAADR33COY7F04821**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Isuzu**  
 Model **KB**  
 Model Year **2000**  
 Color **--**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Seats Condition</b>		<b>المقاعد</b>
01.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	NOT CHECK	حالة الجير النظري
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	DAMAGED	الاطار الامامي
03.B Rear Tyre	DAMAGED	الاطار الخلفي
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	ENGINE NOT START, ALL SYSTEM NOT CHECK	حالة المحرك النظري
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	NOT CHECK	الشاسيه
05.B Chassis Number	VIN CHECKED ONLY PLATE ON LEFT SIDE DOOR	رقم القاعدة
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A Mirror	BOTH SIDE MISSING	المرايا

DEFECT	REMARKS	
06.B AC Condition	NOT CHECK	المكيف
06.C Odometer reading	NOT CHECK	قراءة عداد المسافات
06.D Dash Board	PORTION CRACKED	لوحة القيادة
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Floor	UNDER BODY PARTS, SUSPENTION, FLOOR, CHASSIS NOT CHECK	الارضية
07.B Vehicle Color	WHITE	لون المركبة
07.C Paint	PAINT NOT CHECKED MINOR DENT,SCRATCHES ON BODY,PORTION FADED,PORTION RUSTY	الصبغ
07.D Other	VISUAL TEST ONLY	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.