CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945071
Transaction Date	09 Nov 2026, 15:17:56
Site Name	840 - Emirates Auctions
Transaction Number	48053261 (CC10013) (CC10013)



Vehicle Details

Chassis Number	WDBSK54F99*******
Specification	GCC Specification
Make	Mercedes
Model	SL 500
Model Year	2009
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Bonnet	LOGO MISSING	غطاء المحرك
01.F Trunk	NOT CHECK	صندوق
01.G Fuel Tank	DENT	خزان الوقود
01.H Vehicle Model	SL 280	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY DIRTY PORTION GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Other	UPPER COVER & COMPONENTS PART MISSING	اخري
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY KEY MISSING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT CRACK	حالة المقاعد

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2020 EXPIRED CRACKED	الاطار الامامي
07.B Rear Tyre	2020 EXPIRED CRACKED	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK	ممتص الصدمات
10.B Other	ALL BUSHES DRY CRACK CUT	اخري
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED / CENTER CONSOLE BOX COVER WORN OUT	اخري
11.B Mirror	RIGHT SIDE VIEW MIRROR INDICATOR COVER CRACK	المرايا
11.C AC Condition	NOT CHECKED	المكيف
11.D Dash Board	GETTING FADED PORTION WORN OUT CRACKED	لوحة القياده
11.E Sun Visor	LOOSE	حاجب الشمس
11.F Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.G Door Panel	PORTION WORN OUT CRACK	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB & PANEL WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae