



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 May 2022, 16:50:24
Transaction Number	71101914 (CC10006)	Queue Number	312309



Chassis Number	SALLMAM549A298051
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	HSE
Model Year	2009
Color	Blue
Mileage	193587 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
01.B Trunk	PORTION REPAIRED, REPAINTED & REFITTED	صندوق
01.C Doors	REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	أبواب
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.E Roof	REPAINTED	السقف
02 Tires and Rims Condition		الاطارات
02.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2019/2017 & EXPIRED	الاطار الامامي
03 Suspension System		ممتص الصدمات
03.A Arms	CONTROL ARM BUSHES CRACKED	ازرع
03.B Ball Joint	BOOT CUT	مفصل كروي
04 Steering Condition		المقود
04.A Axle	FRONT LEAK	اكسلات
04.B Tie Rod End	BOOT CUT	مؤخرة الرودادات

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05.B Road Test	NOT CHECK	فحص علي الطريق
05.C Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
06 Engine Condition		المحرك
06.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظرى
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Roof Ceiling	LOOSE	بطانه السقف
08 Exhaust System		نظام العادم
08.A Modification	MODIFIED,REWELDED, NOISY	تعديلات
09 Chassis Condition		الشاسي
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.