



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>13 Nov 2022, 10:27:16</b>
Transaction Number	<b>17354565 (CC10009)</b>	Queue Number	<b>621234</b>



Chassis Number	<b>WP1ZZZ92ZDLA80383</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Porsche</b>
Model	<b>Cayenne S</b>
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>125480 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Door Panel	FRONT RIGHT SIDE LOOSE	لوحة بطانة الباب
01.B AC Condition	OK	المكيف
01.C Power Window Switch	REAR RIGHT SIDE SWITCH LOOSE	مفتاح النافذه
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Bonnet	REPAINTED & REFITTED	غطاء المحرك
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
02.D Doors	FRONT LEFT SIDE , REAR RIGHT SIDE PORTION REPAIRED REPAINTED	أبواب
02.E Fenders	FRONT BOTH SIDE REPAINTED & REFITTED	مدكار
02.F Other	FRONT BUMPER FRAME BULK HEAD LEFT SIDE FENDER FRAME REPAIRED	اخرى
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	JERKING, SIGN OF OIL WET	حالة الجير النظري

DEFECT	REMARKS	
03.C Gear Box Mount	MOUNT CRACK	كرسي الجير
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSH CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2021/2018	الاطار الامامي
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	MINOR OIL LEAK .	حالة المحرك النظري
06.B Mount	MOUNT RUBBER CRACKED	كرسي
06.C Smoke	MINOR BLACK SMOKE	دخان
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	FRONT LEFT SIDE CHASSIS END MINOR DENT , CROSS MEMBER REPAIRED	الشاسيه
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الروداد
<b>09 Seats Condition</b>		<b>المقاعد</b>
09.A Seat Belt	RIGHT SIDE BOTH NOT WORKING	حزام الأمان
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	C 20016 Dubai Private
Chassis No :	WP1ZZZ92ZDLA80383
Vehicle Make :	PORSCHE
Vehicle Model :	CAYENNE S
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	125484 Kms.
Origin : Germany	Model Year : 2013
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : M4802D009...	Horse 300
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 8
G. V. W. : 2500 Kgs.	Empty 2000 Kgs.
	Weight :

⚠ Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-18122160
Inspection Date :	17-11-2022
Certificate Print Date :	22-11-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	12 min 20 sec
Appointment Ref Number :	--
Start Time : 13:20	End Time : 13:32
Lane : 02	Token No. : 162
Attempt : 1	Prints No : 2

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
2 %	6 %	5 %	0 %
Vehicle on Petrol HC Reading			
44 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tire	Date of manufactured tampered or expired	Major
CHANGE FRONT RIGHT SIDE CRACK		
Tinted	Dark	Major
REMOVE FRONT TINT		
Axles	Worn-out axle joint, boot (Major)	Major
CHANGE LEFT SIDE BOOT		
Front Seat belts	Defective	Major
CHANGE FRONT RIGHT SIDE		

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3600	4800	

Inspection Remarks: UNDER BODY COVERED //

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
30544	Cash	18122160	AED 170 Collected on 17/11/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Shawkat Mohamed Samir

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.