CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941234
Transaction Date	04 Nov 2026, 16:46:52
Site Name	840 - Emirates Auctions
Transaction Number	11772112 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JN8FY15Y83*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2003
Color	Blue
Mileage	55094 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR SCRATCHES DENT , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENSION GETTING RUSTY	صدأ
01.C Bonnet	REFITTED	غطاء المحرك
01.D Pillars	LEFT SIDE B/PILLAR ROCKER PANEL REPAIRED	القوائم
01.E Sign of front accident	BUMPER FRAME , FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL , BUMPER FRAME , QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
01.G Vehicle Color	BLUE / BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME BOTH SIDE FRONT & REAR REPAIRED , BEND ,MINOR BULGED , GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START , ALL SYSTEM NOT CHECK , REFITTED PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Other	INTERIOR PARTS MODIFIED , REFITTED	اخري
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST PIPE CUT REWELDED	تعديلات

Condition	Remarks	الحالة
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECK , OPEN REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Dash Board	LEATHER REPLACED , REFITTED	لوحة القياده
11.D Door Panel	LEATHER REFITTED , PORTION DAMAGE	لوحة بطانة الباب
11.E Steering Wheel and control buttons	LEATHER REPLACED , MODIFIED , LOGO DAMAGE	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae