CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934071
Transaction Date	03 Nov 2026, 12:49:41
Site Name	840 - Emirates Auctions
Transaction Number	97197497 (CC10010) (CC10010)



Vehicle Details

Chassis Number	3N1BC1C61B*******
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2011
Color	Black
Mileage	374055 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY N REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Door Handle &Lock	RIGHT SIDE OUTER LOCK COVER MISSING.	مقابض الأبواب والأقفال
01.F Sign of front accident	BUMPER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
01.G Sign of side accident	QUARTER PANEL ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END DENT ,GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Smoke	WHITE	دخان
03.C Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY PORTION LOOSE	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING DELAY SHIFTING COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025/ LEFT SIDE PUNCTURE.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 DRY CRACKED.	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Tail Light	CRACKED /.	الضوء الخلفي
07.C Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Steering Condition		المقود
10.A Steering Box	OIL LEAK ,HARD.	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
11.B Mirror	PORTION FADED	المرايا
11.C AC Condition	LOW COOLING	المكيف
11.D Power Window Switch And Glass	SWITCH ASSEMBLY DAMAGED .	مفتاح النافذه و الزجاج
11.E Dash Board	PORTION CRACKED.	لوحة القياده
11.F Roof Ceiling	PORTION LOOSE	بطانه السقف
11.G Door Panel	WORN OUT PORTION DAMAGED.	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**