



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27791297	Plate Category	: PRIVATE
Transaction Date	: 12 JUL 2021 13:55:46	Plate Number	: 149184 EA
Queue Number	: 366547	Import Doc. Ref.	:
Chassis Number	: 6G1EK52B98L149184	Manufacturer/Model	: CHEVROLET/LUMINA
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.02 - Paint		الصنع
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرآيا الجانبية
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted		أثر صنع في المركبة

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط  
تسجيل غير مسؤولة عن العيوب الخفية

# Test Certificate



Vehicle  
Registration



✓ PASS

Possession Certificate : 65504949

Chassis No : 6G1EK52B98L149184

Vehicle Make : CHEVROLET

Vehicle Model : LUMINA

Vehicle Class : Light Vehicle

Body Type : SALOON

Fuel : Benzene

Color : Black

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 126046 Kms.

Origin : United States Model Year : 2008

Gear Type : -- Engine Size : 5600 CC

Engine No : 18L149184 Horse Power : 198

Axles No : 2 Cylinders : 8

No Of Doors : 4 No Of Seats : 5

G. V. W. : 1850 Kgs. Empty Weight : 1714 Kgs.

Certificate Number : 5-TAS-2021-14622161

Inspection Date : 14-07-2021

Certificate Print Date : 14-07-2021

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Emirates Auction

Total Time Taken :  
9 min 20 sec

Appointment Ref Number : --

Start Time : 14:54

End Time : 15:04

Lane : 01

Token No. : 13

Attempt : 1

Prints No : 1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption ( Rate last 12 Months )



9214 KM

Distance per  
year



949 L

Fuel consumed  
per year



1538 AED

Fuel cost per  
year



2.3 ton

Carbon footprint  
per year

## Parameter Readings

Service brake imbalance on  
front axle  
10 %

Service brake imbalance on  
rear axle  
9 %

Parking brake imbalance  
between LHS and RHS  
6 %

Vehicle on Petrol CO  
Reading  
0.55 %

Vehicle on Petrol HC  
Reading

136 PPM VOL

## Inspection Remarks:

Rear compartment panel, rear left side frame member end repaired, minor engine oil leak, body minor dents and scratches. front bumper, bulk head repaired.

## Payment Details

Inspection Performed by  
59460

Parking Slot No  
--

Payment Method  
VTP Credit Account

Service Name  
Registration Test

Transaction Number  
14622161

Attempt  
1

Service Fees

AED 170 Collected on 14/07/2021

Received by

Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

