



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>23 Jun 2022, 15:43:40</b>
Transaction Number	<b>87729701 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1FTMF1EW9AKA98695</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Ford</b>
Model	<b>F 150</b>
Model Year	<b>2010</b>
Color	<b>Black</b>
Mileage	<b>47867 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION RUSTY	الصبغ
02.B Floor	RUNNING BOARD REPAIRED	الارضية
02.C Pillars	OUTER PANEL REPAINTED , PORTION REPAIRED	القوائم
02.D Windshield	FRONT WIND SHIELD SPOT CRACKED	زجاج
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03.B Tail Light	REAR LEFT SIDE CRACKED	الانارة
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	OK	الشاسيه
<b>05 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	JERKING	حالة الجير النظرى
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
06.B Leaf Spring	LEAF SPRING BUSHES CRACKED	
06.C Suspension Subframe	FRONT SUBFRAME, CROSSMEMBER, LOWER ARM MOUNT BEND	
<b>07 Exhaust System</b>		<b>نظام العادم</b>
07.A Modification	CATAYLIC CONVERTER OPEN ,REWELDED,EXHAUST PIPE REWELDED,NOISY	تعديلات
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	SIGN OF LEAK	حالة المحرك النظرى
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Axel	BOOT CUT	اكسلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.