CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899790
Transaction Date	23 Oct 2026, 16:00:04
Site Name	840 - Emirates Auctions
Transaction Number	79552551 (CC10021) (CC10021)



Vehicle Details

Chassis Number	2G11Z5S37K*******
Specification	Imported
Make	Chevrolet
Model	Impala
Model Year	2019
Color	Black
Mileage	171768 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED , BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH CRACK , WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH CRACK	الاطار الخلفي

Condition	Remarks	الحالة
06 Brake Condition		الفرامل
06.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE PANEL PORTION WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Audio	DISPLAY LCD PORTION FADED	صوتيات
08.D Dash Board	PORTION WORN OUT	لوحة القياده
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae