CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2890801
Transaction Date	20 Oct 2026, 16:41:09
Site Name	840 - Emirates Auctions
Transaction Number	44215101 (CC10013) (CC10011)



Vehicle Details

Chassis Number	5N1ANON64C*******
Specification	GCC Specification
Make	Nissan
Model	Xterra
Model Year	2012
Color	White
Mileage	616142 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.E Bumper	MISALIGN SCRATCHES	دعامية
01.F Windshield	SPOT CRACK	زجاج
01.G Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Trunk	LUGGAGE SHADE MISSING	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME GETTING RUSTY / RIGHT SIDE MIDDLE INNER BEND / DENT	الشاسيه
02.B Chassis Number	CORRECT VIN NUMBER (5N1AN0N64CC521725)	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	COMPONENTS REFITTED , MUDDY , DIRTY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Fog light	LOOSE	كشاف الضباب
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	MINOR LEAK	ممتص الصدمات
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		**الحاله الداخليه**
09.A Other	CENTER CONSOLE BOX COVER WORN OUT,REAR CUP HOLDER DAMAGED MISSING,INTERIOR PARTS GETTING RUSTY	اخري
09.B Mirror	CENTER VIEW MIRROR GETTING FADED	المرايا
09.C AC Condition	OK	المكيف
09.D Dash Board	GLOVE BOX COVER MISALIGN	لوحة القياده
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae