CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934057
Transaction Date	04 Nov 2026, 14:24:08
Site Name	840 - Emirates Auctions
Transaction Number	41366684 (CC10013) (CC10013)



Vehicle Details

Chassis Number	WDB2200671*******
Specification	Imported
Make	Mercedes
Model	S 350
Model Year	2003
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION COVERED DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK , RADAR SENSOR MISSING	دعامية
01.E Trunk	NOT OPEN	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FULLY COVERED MUDDY DIRTY PORTION GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT CRACK	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	MODIFIED	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		**الاطارات**
07.A Front Tyre	2023 DRY CRACK	الاطار الامامي
07.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
08 Lights		**الاضاءة**
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Brake Condition		**الفرامل**
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		**ممتص الصدمات**
10.A Arms	LOWER ARM BUSHES CUT	ازرع
11 Steering Condition		**المقود**
11.A Steering Boot	BOOT CUT	ربلة المقود
11.B Tie Rod End	BOOT CUT	مؤخرة الرودات
11.C Axle	BOOT CUT	اكسلات
12 Interior Condition		**الحاله الداخليه**
12.A Other	INTERIOR PARTS GETTING RUSTY	اخري
12.B AC Condition	NOT CHECKED	المكيف
12.C Dash Board	GETTING FADED PORTION WORN OUT	لوحة القياده
12.D Odometer reading	NOT CHECKED	قراءة عداد المسافات
12.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
12.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12.H Engine Start Button	SMART KEY MISSING	زر تشغيل المحرك
13 Engine Cooling System		**نظام تبريد المحرك**
13.A Coolant tank	WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae