

Queue Number

2619021

Transaction Date

05 Aug 2026, 17:03:33

Site Name

840 - Emirates Auctions

Transaction Number

89839096 (CC10010) (CC10011)



Vehicle Details

Chassis Number	5FNYF48519*****
Specification	GCC Specification
Make	Honda
Model	Pilot
Model Year	2009
Color	Grey
Mileage	255082 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORION REPAIRED,DENTS SCRATCHES,PORION GETTING RUSTY	الصبغ
01.C Doors	FRONT BOTH SIDE,REAR RIGHT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED MINOR DENT	الارضية
01.F Bumper	MISALIGN,PORION CRACK	دعامية
01.G Bonnet	REPAIRED REPAINTED,REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE C/PILLAR OUTER PANEL PORTION REPAIRED REPAINTED	القوائم
01.I Trunk	REPAINTED PORTION REPAIRED,FRONT SWITCH NOT WORKING,LETTER MISSING	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED, MUDDY OILY CHECKED VISIBLE AREA ONLY / OK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	MOUNT BOLT LOOSE FROM ENGINE SIDE.	كرسي
03.B Smoke	WHITE	دخان

Condition	Remarks	الحالة
03.C Engine Visual Condition	OIL LEAK , OPEN REFITTED.	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED,CRACKED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK , REFITTED , JERKING.SHIFTING DELAY .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
05.C Four Wheel Drive	NOT WORKING PROPERLY .	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.B Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	CAP MISSING,.	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS FADED,LEFT SIDE PORTION CRACKED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
09.B Disc&Drum	PARTS GETTING RUSTY.	دسك وطناير الفرامل
10 Suspension System		ممتص الصدمات
10.A Other	SUSPENSION PARTS CHANGED .	اخرى
11 Steering Condition		المقود
11.A Axle	BOOT CUT GREASE LEAKING.	اكسلات
12 Interior Condition		الحالة الداخلية
12.A Other	INTERIOR PARTS GETTING RUSTY,WATER FLOODED	اخرى
12.B Mirror	RIGHT SIDE COVER LOOSE,CENTER VIEW MIRROR FADED	المرآيا
12.C AC Condition	OK	المكيف
12.D Dash Board	GLOVE BOX COVER PORTION LOOSE	لوحة القيادة
12.E Door Panel	PORTION CRACK WORN OUT,LOOSE	لوحة بطانة الباب
12.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.G Gear Shifting Lever	KNOB GETTING WORN OUT,PANEL COVER PORTION CRACK	ذراع نقل السرعات
12.H Engine Start Button	REMOTE DAMAGED FIX BY TAPE	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae