

Queue Number 2703586

Transaction Date 31 Aug 2026, 16:42:14

Site Name
840 - Emirates AuctionsTransaction Number
74695755 (CC10009) (CC10012)

Vehicle Details

Chassis Number	1GKUKMEF5A*****
Specification	GCC Specification
Make	GMC
Model	Yukon
Model Year	2010
Color	White
Mileage	373074 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة	
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.B Doors	REAR RIGHT SIDE PORTION REPAINTED PORTION REPAIRED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION DENT, MUDDY	الارضية
01.E Bumper	MISALING	دعامية
02 Chassis Condition	الشاسي	
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED PORTION RUSTY,OK	الشاسيه
03 Engine Condition	المحرك	
03.A Other	COOLANT WATER LEAK	اخرى
03.B Engine Visual Condition	OIL LEAK OPEN REFITTED	الحالة النظرية للمحرك
04 Seats Condition	المقاعد	
04.A Seat Belt	FRONT LEFT SIDE LOOSE	حزام الأمان
04.B Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition	الجير	
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED, PARTS GETTING RUSTY, MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص على الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	RIGHT SIDE 2024 , LEFT SIDE 2025	الاطار الخلفي
06.C Rims Condition	FRONT LEFT SIDE HUB MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	FADED	الضوء الخلفي
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED	اخرى
08.B Mirror	BOTH SIDE FOLDING NOT WORKING	المرآيا
08.C AC Condition	LOW COOLING	المكيف
08.D Floor Matting	EXTRA COVER	فرش الأرضيه
08.E Dash Board	PORTION CRACK , LEATHER REPLACED , PORTION LOOSE	لوحة القيادة
08.F Sun Visor	RIGHT SIDE COVER MIRROR MISSING	حاجب الشمس
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae