

Queue Number 2827635

Transaction Date 03 Oct 2026, 13:00:29

Site Name
840 - Emirates AuctionsTransaction Number
18321440 (CC10021) (CC10021)

Vehicle Details

Chassis Number	WBAKR6102G*****
Specification	GCC Specification
Make	BMW
Model	X5
Model Year	2016
Color	White
Mileage	187658 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	BOTH RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED,CHECKED VISIBLE AREA ONLY	الارضية
01.F Trunk	PORTION REPAINTED,PORTION REPAIRED	صندوق
01.G Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED,MINOR OIL LEAK,ABNORMAL NOISY,SHAKING,RPM NOT STABLE	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT LEFT COVER DAMAGED	حالة المقاعد
---------------------	--------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED,PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	------------------------------	----------------------

05.B Road Test	NOT CHECK	فحص علي الطريق
----------------	-----------	----------------

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	الزرع
09 Interior Condition		الحالة الداخلية
09.A AC Condition	OK	المكيف
09.B Roof Ceiling	PORTION LOOSE	بطانه السقف
09.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae