

TEST CERTIFICATE

Site Number
Transaction Number

03.B Front Tyre

840-Emirates Auctions 58226994 (CC10006) Transaction Date

10 Aug 2022, 13:16:45

الاطار الامامى

Queue Number

312309



Chassis Number 1N4AL3AP1DC148211

Engine Number

Vehicle Class Car

Manufacturer Nissan

Model Altima

Model Year 2013

Color Grey

Mileage 130222 Miles

Fuel Type Petrol

No. Of Cylinders

Specification USA Imported

DEFECT REMARKS

O1 Body قبت قبل المادي الم		
01.A Other	VEHICLE SIGN OF WATER FLOODED	اخري
01.B Sign of front accident		وجود مؤشر لحادث في المقدمة
01.C Fenders	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED & REFITTED	مدكار
01.D Bonnet	PORTION REPAIRED, REPAINTED & REFITTED	غطاء المحرك
01.E Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ

 01.F Doors
 FRONT BOTH SIDE REPAINTED

 01.G Paint
 BODY PORTION REPAINTED,PORTION REPAIRED,MINOR

DENT,SCRATCHES

الشاصي O2 Chassis Condition

O2.A Chassis OK ميال الشاسية O3 Tires and Rims Condition

الاطار الخلفي BOTH SIDE 2018 الاطار الخلفي

BOTH SIDE 2018

O4 Transmission Condition الجير

فحص علي الطريق NOT CHECK

DEFECT	REMARKS	
04.B Visual Gear Box Condition	OK	حالة الجير النظرى
Condition		
05 Interior Condition		الحاله الداخليه
05.A AC Condition	OK	المكيف
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Engine Condition		المحرك
07.A Visual Engine Condition	OK	حالة المحرك النظرى
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.