CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972868
Transaction Date	11 Nov 2026, 17:02:59
Site Name	840 - Emirates Auctions
Transaction Number	13036887 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JN8AY25Y4C*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2012
Color	Black
Mileage	125328 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	PORTION GETTING RUSTY, MUDDY	الارضية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	COMPARTMENT COVER LOCK HANDLE DAMAGED	صندوق
01.H Sign of front accident	BUMPER FRAME BEND,FENDER FRAME,RADIATOR FRAME SUPPORT REPAIRED,	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME THICK RUST PROOFED,GETTING RUSTY,CRASH BOX BEND	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT ,PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY,MINOR JEKRING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED GETTING RUSTY	اخري
09 Steering Condition		المقود
09.A Steering Oil	OIL WET	زيت المقود
09.B Steering Boot	RIGHT SIDE BOOT CUT	ربلة المقود
10 Interior Condition		الحاله الداخليه
10.A Other	COOL BOX NOT WORKING,REAR CUP HOLDER DAMAGED,INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
10.B AC Condition	OK	المكيف
10.C Dash Board	LEATHER REPLACED.PORTION LOOSE	لوحة القياده
10.D Sun Visor	RIGHT SIDE LOOSE FIX BY DOUBLE TAPE	حاجب الشمس
10.E Door Panel	PORTION CRACK WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر wecare@carscheck.ae