



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 Jan 2023, 17:03:09**
 Transaction Number **62365571 (CC10009)** Queue Number **661587**



Chassis Number **3N1BC1A78CK258459**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Tiida**
 Model Year **2012**
 Color **White**
 Mileage **215594 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Other	STIBILZER LINK BOOT CUT	اخرى
01.B Arms	LOWER ARM BUSHES CUT	ازرع
01.C Ball Joint	BOOTCUT	مفصل كروي
01.D Shock Absorber	LEAK	ممتص الصدمات
02 Steering Condition		المقود
02.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
02.B Steering Oil	MINOR OIL LEAK	زيت المقود
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER CRACKED	كرسي
03.B Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,OIL LEAK REFITTED	حالة المحرك النظري
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	NOT CHECKED	حالة الجير النظري
04.B Road Test	NOT CHECKED	فحص علي الطريق
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير

DEFECT	REMARKS	
05 Chassis Condition		الشاسي
05.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
06 Body		جسم المركبة
06.A Floor	UNDER FLOOR PARTS CHASSIS THICK RUST PROOFED	الارضيه
06.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES ON BODY	الصبغ
06.C Sign of back accident		وجود مؤشر لحادث في الخلف
06.D Bumper	DAMAGED / PORITON LOOSE	دعامية
06.E Sign of front accident		وجود مؤشر لحادث في المقدمة
06.F Other	FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT FENDER FRAME REPAIRED	اخرى
07 Interior Condition		الحاله الداخليه
07.A Odometer reading	NOT CHECKED	قراءة عداد المسافات
07.B AC Condition	NOT CHECKED	المكيف
07.C Other	HANDREST COVER DAMAGED	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.