



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Apr 2022, 14:45:41
Transaction Number	64043275 (CC10006)	Queue Number	312309



Chassis Number	WBABN51060JT83438
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	330
Model Year	2002
Color	Black
Mileage	215283 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Japan Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
01.C Dash Board	CRACKED	لوحة القيادة
01.D Other	FRONT LEFT SIDE INNER CONSOLE BOX COVER MISSING & MIDDLE DAMAGED	اخرى
02 Body		جسم المركبة
02.A Fenders	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED & REFITTED	مدكار
02.B Bonnet	REPAIRED REPAINTED & REFITTED	غطاء المحرك
02.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
02.D Floor	FRONT LEFT SIDE FLOOR HAVE MINOR DNET	الارضية
02.E Other	BONNET OPENING HANDLE DAMAGED & MODIFIED	اخرى
03 Engine Condition		المحرك
03.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظري
04 Transmission Condition		الجير

DEFECT	REMARKS	
04.A Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Propeller Shaft	BOOT CUT	ناقل الحركة
05 Suspension System		ممتص الصدمات
05.A Shock Absorber	MODIFIED	ممتص الصدمات
06 Tires and Rims Condition		الاطارات
06.A Spare Tire & Tools	SPARE TIRE & TOOLS MISSING	الاطار الاحتياطي و العدة
06.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.C Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07.B Fog light	NOT WORKING	كشاف الضباب
07.C Head Light	BOTH SIDE PARK LIGHT NOT WORKING	الاضاءة الرئيسية
08 Chassis Condition		النشاصي
08.A Chassis Number	CHASSIS NUMBER CHECK ONLY FRONT RIGHT SIDE FLOOR	رقم القاعدة
08.B Chassis	OK	النشاصيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.