CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966535
Transaction Date	10 Nov 2026, 15:56:55
Site Name	840 - Emirates Auctions
Transaction Number	76969948 (CC10008) (CC10011)



Vehicle Details

Chassis Number	2FMHK6C82F*******
Specification	GCC Specification
Make	Ford
Model	Flex
Model Year	2015
Color	White
Mileage	130231 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT SIDE REFITTED,REAR LEFT PORTION REPAIRED REPAINTED & REAR RIGHT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,PAINT THICKNESS HIGH,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE LOWER DOOR DENT ,REAR RIGHT REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	REAR QUATER PANEL RUSTY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	PORTION REPAIRED REPAINTED,REFITTED	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME MINOR BEND	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS END MINOR DENT ,REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED ,DENT	الشاسيه
02.B Chassis Number	VIN CHECKED ON WHISHILED ,LEFT SIDE STICKER ONLY	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Mount	MOUNT BUSHES CRACKED	كرسي
03.B Engine Visual Condition	COMPONENTS REFITTED	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OK	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 WORN OUT CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	SOME WARNING LIGHT HIDDEN ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER LEATHER MINOR CRACK LOCK DAMAGED NOT CLOSE,INTERIOR PARTS GETTING RUSTY	اخري
10.B AC Condition	OK	المكيف
10.C Audio	SWITCH DAMAGED	صوتيات
10.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Sunroof	REAR CURTAIN PORTION DAMAGED LOOSE	فتحت سقف
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.