

04.A Visual Gear Box

TEST CERTIFICATE

حالة الجير النظرى

Site Number 840-Emirates Auctions Transaction Date 24 May 2023, 13:40:59

Transaction Number 46484129 (CC10010) Queue Number 719238



Chassis Number KNAFJ4113G5915957

Engine Number

Vehicle Class Car Manufacturer Kia

Model Cerato

Model Year 2015
Color Silver
Mileage 001 Km

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

01 Tires and Rims Condition		الاطارات
01.A Rear Tyre	BOTH SIDE 2019 CRACKED ,EXPIRED.	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2019 CRACKED.	الاطار الامامي
02 Battery Condition		حالة البطارية
02.A Battery Condition	MISSING.	حالة البطارية
O3 Body		جسم المركبة
03.A Bonnet	PORTION REPAINTED.	غطاء المحرك
03.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
03.C Paint	BODY PORTION REPAIRED ,PORITON REPAINTED ,DENTS SCRATCHES ,PORTION FADED.	الصبغ
03.D Doors	LEFT SIDE REPAINTED ,PORTION REPAIRED.	أبواب
03.E Fenders	REAR LEFT SIDE QUARTER PANEL ,WHEEL ARCH REPAINTED ,PORTION REPAIRED.	مدكار
03.F Vehicle Year Model	2016	سنة صنع المركبة
03.G Floor	PORTION DENT.	الارضية
04 Transmission Condition		الجير

NOT CHECKED.

DEFECT	REMARKS	
Condition		
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Engine Condition		المحرك
05.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING.	حالة المحرك النظرى
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Arms	LOWERARM BUSHES CRACKED.	ازرع
07.B Shock Absorber	WEAK,LEAK .	ممتص الصدمات
08 Interior Condition		الحاله الداخليه
08.A AC Condition	NOT CHECKED .	المكيف
08.B Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
08.C Odometer reading	NOT CHECKED .	قراءة عداد المسافات
09 Chassis Condition		الشاصي
09.A Chassis	CECKED ONLY VISIBLE AREA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.