



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>01 Aug 2022, 16:49:18</b>
Transaction Number	<b>60980209 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1N4AA5APXCC840550</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Maxima</b>
Model Year	<b>2012</b>
Color	<b>Silver</b>
Mileage	<b>229442 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT COOLING	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
02.B Head Light	LENS FADED	الاضاءة الرئيسية
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Fenders	FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
03.B Paint	BODY PORTION REPAIRED,REPAINTED & DENT SCRATCHES,PORTION FADED	الصبغ
03.C Doors	REAR LEFT SIDE HAVE DEEP DENT	أبواب
03.D Floor	UNDER FLOOR THICK RUST RUST PROOFEDFRONT RIGHT SIDE CHASSIS TOO MUDDY & OILY CHECKED VISIBLE AREA	الارضية
03.E Bumper	MISALIGN	دعامية
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد

DEFECT	REMARKS	
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	MINOR OIL LEAK ,	حالة الجير النظرى
05.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادت
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED,LOW AIR	الاطار الامامي
08.B Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
08.C Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	OIL LEAK & TOTALY MUDDY	حالة المحرك النظرى
09.B Smoke	MINOR BLACK SMOKE	دخان
09.C Mount	MOUNT RUBBER CUT	كرسي
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.