



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	: 0
Transaction Number	: 19556106	Plate Category	: PRIVATE
Transaction Date	: 01 APR 2020 09:00:45	Plate Number	: 280803 EA
Queue Number	: 165534	Import Doc. Ref.	:
Chassis Number	: WBAFG81078L280803	Manufacturer/Model	: BMW/X6
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 186638

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
		FRT LHS SHOCK ABSORBER WEAK
04 Tires Rims		الاطارات والعجلات
04.04 - Rear Left And Right Hand Tires		الاطارات الخلفية
05 Body		الهيكل
05.02 - Paint		الصيغ
		BODY PORTION DENT & SCRATCHES
05.07 - Floor		الارضية
		UNDER BODY FULLY COVERD
06 General Items		الاشياء العامة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		ROAD TEST NOT DONE & VEHICLE GETTING OFF ,MISFIRE
09 Auction		الفحص الكامل
09.06 - Chassis Ok		الشاصي جيد
		OK
09.10 - Engine Oil Leaking		تهريب زيت المحرك
		ENG OIL LEAK
The Test Certificate Shows the test Result at the time of inspection only.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط		