



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 Jan 2023, 16:16:57
Transaction Number	40771562 (CC10010)	Queue Number	655656



Chassis Number	JNKBV61E58M201211
Engine Number	
Vehicle Class	Car
Manufacturer	Infiniti
Model	G35
Model Year	2008
Color	Grey
Mileage	151726 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Other	GEAR KNOB WORN OUT	اخرى
01.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب
01.D Dash Board	CRACKED,PORTION DAMAGED	لوحة القيادة
01.E Audio	SCREEN PORTION FADED	صوتيات
01.F Sun Visor	LEFT SIDE LOOSE,GLASS COVER MISSING	حاجب الشمس
02 Chassis Condition		الشاسي
02.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
03 Engine Condition		المحرك
03.A Visual Engine Condition	REFITTED.	حالة المحرك النظري
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	REFITTED.	حالة الجير النظري
04.B Propeller Shaft	CENTER BUSHES CRACKED ,	ناقل الحركة
04.C Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Floor	UNDER FLOOR COVERED ,CHECKED ONLY VISIBLE AREA ,RUNNING BOARD FLOOR PORTION DENT .	الارضية
05.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
05.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
05.D Bonnet	REFITTED,LEFT SIDE STAY SHOCK MISSING ,RIGHT SIDE WEAK.	غطاء المحرك
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2019,	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2019,	الاطار الامامي
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACK..	ازرع
08 Exhaust System		نظام العادم
08.A Other	PORTION DENT .	اخرى
09 Wipers and Arms		المساحات
09.A Other	WATER TANK CAP MISSING.	اخرى
10 Lights		الاضاءة
10.A Warning Light	WARNING MASSAGE ON DISPLAY	ضوء تحذير
11 Seats Condition		المقاعد
11.A Seat Condition	DRIVER SEAT PORTION CUT	حالة المقاعد
12 Steering Condition		المقود
12.A Steering Box	MINOR OIL LEAK .	جهاز المقود
12.B Tie Rod End	BALL JOINT BOOT LEAK.	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.